








4x hole $\phi 4 \times 15$, screw 4,8x25, steel washer

TOLERANCE: +3/-3 mm

CORVUS 510 C